

Mine Name: Milehigh 1

Operator Name: William Chirnside

Inspector(s): Wayne Western & Brett Gregory

State of Utah **DEPARTMENT OF NATURAL RESOURCES** Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director

JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program

June 22, 2009

	onen
Reviewed:	1110

Permit Number: S/023/0060

Time: 3:00 - 3:20 pm

Inspection Date: June 17, 2009

Other Participants: None		Mine Status: Active		
	Elements of Inspection	Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer, Bonds	\boxtimes	\boxtimes	
2.	Public Safety (shafts, adits, trash, signs, highwalls)			
3.	Protection of Drainages / Erosion Control			
4.	Deleterious Material			
5.	Roads (maintenance, surfacing, dust control, safety)			
6.	Concurrent Reclamation			
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8.	Water Impoundments			
9.	Soils	\boxtimes	\bowtie	
10	. Re-vegetation			
11	. Air Quality	$\overline{\Box}$		

Bond Amount:

12. Other

Bond \$1,500 posted in 2007.

Permit fee:

Fee paid July 18, 2008.

Purpose of Inspection:

Routine Inspection.

Inspection Summary:

The site consisted of a small pit that is approximately 6 feet deep. The disturbed area is approximately 0.2 acres. The overburden and stockpiles are piled next to the pit. The area appears to be stable, and there are no signs of erosion. No equipment is stored on site.

The Permittee did not stockpile topsoil.



Inspection Date: June 17, 2009 Page 2 of 3 S/023/0060

Directions:

See map in GIS file. Drive north on main road past site and the turn south on 2-track road.

Conclusions and Recommendations:

The Division should continue to monitor the site and evaluate the bond in 2010.

Inspector's Signature

WHW BG

cc: William Chirnside, Operator Jerry Mansfield, BLM

Attach - GIS

O:\M023-Juab\S0230060-Milehigh\inspections\ins-06172009.doc



